

CONFIDENTIAL

K-7381

NPIC/CSD-110/66
24 FEBRUARY 1966
PAGE 4 OF 6

25X1

HIGHWAY BRIDGE
ROUTE 154, NORTH VIETNAM
2034N 10500E

1. SIGNIFICANCE:

THIS BRIEFING BOARD REVEALS THE DAMAGED HIGHWAY BRIDGE OVER THE NAM XIA (RIVER) AND THE NEWLY-CONSTRUCTED BY-PASS TO THE BRIDGE.

2. REMARKS:

THE NAM XIA IS A TRIBUTARY OF THE SONG MA (RIVER).

3. LOCATION:

THE BRIDGE IS LOCATED APPROXIMATELY 0.1 NM WEST OF THE JUNCTION OF ROUTES 15 AND 154.

4. MISSION READOUT:

REVEALS AIR STRIKE DAMAGE TO THE FIVE... 25X1

SPAN, DECK-TYPE BRIDGE ON ROUTE 154 OVER THE NAM XIA. ONE SPAN IS TOTALLY DESTROYED AND TWO ARE HEAVILY DAMAGED, RENDERING THE BRIDGE UNSERVICEABLE. A BY-PASS HAS BEEN CONSTRUCTED AROUND THE BRIDGE TO THE NORTH.

25X1

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue.

CONFIDENTIAL

Approved For Release 2007/11/13 : CIA-RDP80T01471R001500070001-9

NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER

25X1


CONFIDENTIAL



HIGHWAY BRIDGE

ROUTE 154, NORTH VIETNAM

20-34N 105-00E



CONFIDENTIAL